Responses-to-Comments Table

Date	Department		Comments	Responses
28.8.2023	Drainage	1.	It is shown that catchment runoff from subcatchment C1,	We aim to clarify and expound upon the proposed development to
	Services		although is to be captured by an existing channel at the north	ensure absolute clarity and avoid any potential confusion. Please
	Department		of the site, is inevitably through the proposed site as it	refer to the cover letter and the Appendices for details.
	(DSD) CE/MN of		converges to the existing streamcourse. With the available	
	DSD		structural layout (section Y-Y) provided, the decking of the	We are aware that the subcatchment C1 runoff will likely flow to the
	(Contact Person:		existing streamcourse would suggest that the streamcourse	watercourse adjacent to the Site Boundary and eventually flow to the
	Mr. Samuel		would become more like a pipe flow, rather than an open	watercourse within the site.
	Wang; Tel: 2300		channel flow where the floodplain adjoining the channel may	
	1135)		be utilised in case of small scale overflow.	The watercourse within the site is not like a pipe flow as it is not a full
			the section of such channel would potentially lead to flooding	water flow in a closed conduits or circular cross section. It is remained
			at the immediate upstream of the system. However, no	no change as an open channel. As shown in the Section drawing (see
			hydraulic check has been provided in terms of the natural	Appendix 2), there is void space as deck over area, not covering or
			streamcourse section with the site. Please provide further	restricting the watercourse like a pipe.
			elaboration on the respective hydraulic performance to ease	
			any concern and suspicion of the flood risk related to the	A typical section is provided for easy reference (see Appendix 2). As
			proposed development.	shown, watercourses within and adjacent to the Site are able to flow
				as its existing condition, no changes had been made to the
				watercourse due to the development as all the additional runoff due
				to the development are stored in the underground storage tank.
				There are also perimeter U-channels all along the boundary of the
				site which had been designed with additional capacity that can cater
				additional flow, such as overland flow if any, and they will be leading

Date	Department	Comments	Responses
			into the underground storage tank. The storage tank has also been
			sized with 15% additional buffer storage for contingency. No adverse
			drainage impact is anticipated.
			The capacity of the existing stream within the site area is checked.
			(see Appendix 3) The runoff from Catchment A, part of the
			Catchment C1 and Catchment C2 is considered in the capacity
			checking of the existing stream within the site. With reference to the
			estimation under 50 years return period calculated to our best
			estimation based on the available information, the utilization rate of
			the existing channel under existing situation and after the proposed
			development is 45.6% to 92.6% and 42.7% to 90.3% respectively.
			The above calculation has taken into account the 10%
			sedimentation. No adverse flooding risk is anticipated upon the
			completion of the proposed works.
			Considering that the existing topography would remain almost the
			same with the proposed temporary structure and no adverse flooding
			risk is anticipated upon the completion of the proposed works as
			supported by the technical assessment. Being the operator/user of
			the proposed development, the applicant is also committed to taking
			all necessary measures to prevent any potential flooding issues to
			ensure the smooth and safe operation of the proposed use.

Date	Department	Comments	Responses
		2. It is noted from the existing topography in Appendix 2 and	The site formation level is only higher than adjacent areas locally
		formation level in Figure 3-2 that the site formation level would	within the site area, but there is no change to the level of the
		be altered to be equivalent or higher than the adjacent areas	watercourses. The building is decked over as shown in the typical
		including areas in catchment C3 and C1 after proposed	section attached. There is no change to the flow path for the runoff
		development. Further to your RtC, please advise how the	from subcatchment C3 and C1 before and after the proposed
		overland flow could follow the existing flow path to the existing	development.
		watercourse within the site area. Please also clarify if the	
		flow path of the tributary from the northwest of the site to the	In fact overland flow from Subcatchment C1 will flow from catchment
		watercourse within the site would be affected under the site	C1 flow to the watercourse adjacent to the Site boundary and
		formation level proposal.	eventually flow to the watercourse inside the site following existing
			flow path. If any runoff not captured, it will flow into the perimeter
			drain within the site, the levels are same as existing ground level. No
			change from existing condition.
			Overland flow from C3 is about 0.132m³/s, if any will be collected into
			perimeter drain section CP11 to CP14 and they are shown to have
			more than 0.132m³/s capacity in each of the U-channel segments.
		3. Appendix F – Please advise if adequate headroom is reserved	As shown in the typical section drawing (see Appendix 2), adequate
		for future maintenance of the existing watercourse within the	headroom which is essentially the deck over area. The detailed
		site.	design will be subject to scrutiny during GBP submission, with
			consultation with DSD as deemed necessary.

Date	Department		Comments	Responses
19.9.2023	Drainage	1.	It is noted from the hydraulic checking that some parts (e.g.	Updated. The hydraulic checking of parts 1a to 1, 1 to 2 and 2 to 3
	Services		1a to 1; 1 to 2; 2 to 3) were not included in the submission.	are included in the submission (see Appendix 3).
	Department		Please supplement as appropriate.	
	(DSD) CE/MN of	2.	Please advise the actual condition of the existing stream. One	Site photos (Photo 1 to 7) taken in 2022 showing the actual
	DSD		of the assumptions is that the bedding material is taken as	conditions are attached in the hydraulic checking document for
	(Contact Person:		trapezoidal shotcreted channel. Please justify, with site photo	reference. The photos also show the trapezoidal channel appeared
	Mr. Samuel		if possible.	to be concrete-lined (see Appendix 3).
	Wang; Tel: 2300	3.	Runoff from sub-catchment B is not adopted in the calculation.	Runoff from sub-catchment B is not adopted in the calculation
	1135)		Please advise the respective flow path and confirm if it should	because it does not flow into the sections of watercourse involved
			be considered.	in the hydraulic checking. Flow path of sub-catchment B is indicated
				in Figure 1.1. As shown in Photo 8 to 10, there is an existing drainage
				channel to collect the runoff along sub-catchment B separately (see
				Appendix 3).

Date	Department	Comments	Responses
1.8.2023	Transport Department (TD)	 Section 3.2.2 The applicant shall justify why no traffic survey was conducted but to apply a growth factor to 2018 surveyed data to obtain the base-line traffic flow condition. Table 3.2 - The DFC for Po Shek Wu Road Interchange (i.e. Tai Tau Leng Roundabout) in year 2022 seems to be on the high side. Please review. 	 Please refer to Section 3.2 of the revised TIA report for the justification of using 2018 surveyed data with growth factor applied to obtain the base-line traffic flow condition (See Appendix 5). DFC for Po Shek Wu Road Interchange (Junction RC) has been reviewed and revised, please refer to Table 3.3 and Table 4.4 of the revised TIA report for details (See Appendix 5).
		Figure 2.4 - It seems that the existing street furniture, e.g beam barrier, type II railing, etc. will obstruct the proposed ingress and egress on Lo Wu Station Road. Please indicate any required modification works on the drawing and confirm these modification works are technically feasible. Please also check if the proposed ingress / egress would affect any existing access.	Please refer to Section 2.4.9 and Figure 2.6 of the revised TIA report for modification works of existing street furniture, including beam barrier and type II railing, for the opening of site access (See Appendix 5). Please note that the existing staircase access to maintenance area would be maintained, and related staff could enter via the ramp of the site for maintenance when necessary (See Appendix 5).
		Please be informed that the design year of the TIA should be years after the planned completion of the development. The TIA should be updated if the planned completion date is revised.	 Please note that the design year is revised to 2027, please refer to Table 3.3 and Table 4.4 of the revised TIA report for details of assessments (See Appendix 5).