



Figure 2a Photo showing view from Casa Marina III (VSR 1) towards the site (prior the project).



Figure 2b Photomontage showing view from Casa Marina III (VSR 1) towards the site (after the project without visual impact mitigation measures).



Figure 2c Photomontage showing view from Casa Marina III (VSR 1) towards the site (after the project with visual impact mitigation measures option A).




Figure 2d Photomontage showing view from Casa Marina III (VSR 1) towards the site (after the project with visual impact mitigation measures option B).

\overline{A}					Ŗ					DESIGNED BY AY	DRAVING TITLE	
										drawn by AY	Photomontage- Casa Marina III	
			_		$\downarrow \land$					CHECKED BY KL		
Á					Å					IN CHARGE ST		EIA study for C
$ \Delta $					$ \Delta $					DATE	7	Plant – Executi
REV	DATE	BY SUB A	P	DESCRIPTION	REV	DATE	BY SI	JB APP	DESCRIPTION			

FILE NAME CADD DATE SCALE N.T.S.	
Uve Arup & Partners SCALE NITS	CADD DATE
N Hong Kong Limited L HARDS	N.T.S.
or Cement Works / Concrete Batching	2
cutive Summary	