



Figure 7.4a Photo showing view from Casa Marina III (VSR 1) towards the site (prior the project).



Figure 7.4b Photomontage showing view from Casa Marina III (VSR 1) towards the site (after the project without visual impact mitigation measures).



Figure 7.4c Photomontage showing view from Casa Marina III (VSR 1) towards the site (after the project with visual impact mitigation measures option A).




Figure 7.4d Photomontage showing view from Casa Marina III (VSR 1) towards the site (after the project with visual impact mitigation measures option B).

REV	DATE	BY	SUB	APP	DESCRIPTION

DESIGNED BY	AY
DRAWN BY	AY
CHECKED BY	KL
IN CHARGE	ST
DATE	

DRAWING TITLE	Photomontage- Casa Marina III
---------------	--------------------------------------

ARUP Ove Arup & Partners Hong Kong Limited
JOB TITLE EIA study for Cement Works / Concrete Batching Plant

FILE NAME	CADD DATE
SCALE	N.T.S.
FIGURE NUMBER	7.4
SHEET NO	STAGE CODE REV P 0