

Figure 7.5a Photo showing view from Fortune Garden (VSR 2) towards the site (prior the project).







Figure 7.5c Photomontage showing view from Fortune Garden (VSR 2) towards the site (after the project with mitigation measures option A).



							$ \Delta $					DESIGNED BY	IRAVING TITLE	
							$\left[\Lambda \right]$						_	
							$\overline{\Lambda}$					DRAWN BY AY		
7							$\overline{\Lambda}$					CHECKED BY	Dhatamantana Fartuna Cardan	
Ľ7							$\left \right\rangle$					KL	Photomontage – Fortune Garden	JOB TITLE
17							$\overline{\Lambda}$					IN CHARGE ST		FIA study for Comont W
17							$\overline{\Lambda}$					DATE	_	EIA study for Cement W
RE	$\overline{\mathbf{v}}$	DATE	BY S	UB AP	P	DESCRIPTION	REV	DATE	BY	SUB APP	DESCRIPTION	DATE		Plant