

SUMMARY OF APPROACHES
HONG KONG INTERNATIONAL AIRPORT
0657 – 1044 Hours UTC, 22 August 1999

Aircraft type	Landed	Go-around	Comments
Runway in use 07R			
A330		0657	2 nd go-around @ 0727
A330	0700		
MD82	0710		
MD11	0716		
A320	0721		
A330		0727	Diverted
A330		0735	Diverted
A330		0742	Diverted
Runway change to 25L			
A340		0818	Diverted
B742		0830	Diverted
B744	0849		
A340		0859	Diverted
B773	0915		
B744		0940	Diverted
A330		0945	2 nd approach, landed 1019
B773	0947		
B772	0953		
A330	1002		
A330	1019		
B744	1024		
A340	1029		
B763	1031		
A330		1034	Diverted - airport closed due later accident
B744	1036		
B773	1040		
MD11	1043		Accident flight