



Legend (圖例):

- Site / 工地
- Tree-Health (Proposed treatment) 樹木 - 健康狀況 (處理建議)
- Dead (remove) 枯死 (移除)
 - Very poor health / damaged (remove) 健康非常差 / 損毀 (移除)
 - Good health (remove) 健康良好 (移除)
 - Good / fair / poor health (retain) 健康良好 / 一般 / 差 (保留)
- Landscape Resources 景觀資源
- LR1 - Transport Route 交通路線
 - LR2 - Commercial/Residential/Institutional Building Area 商業/住宅/機構樓宇區
 - LR3 - Building within Declared Monument 位於法定古蹟範圍內的建築物
 - LR4 - Open Space within Declared Monument 位於法定古蹟範圍內的露天空地
 - LR5 - Public Park / Recreational Area 公園/文娛區

Tree ID 樹木編號	Species Name 物種名稱
T1	<i>Bombax ceiba</i> 木棉
T2	<i>Ficus virens</i> 大葉榕
T3	<i>Nageia nagi</i> 竹柏
T4	<i>Celtis sinensis</i> 朴樹
T5	<i>Mangifera indica</i> 芒果
T6	<i>Aleurites moluccana</i> 石栗
T7	<i>Aleurites moluccana</i> 石栗
T8	<i>Plumeria rubra</i> 紅雞蛋花
T9	<i>Araucaria cunninghamii</i> 花旗杉
T10	<i>Ficus microcarpa</i> 細葉榕
T11	<i>Dracaena marginata</i> 馬尾鐵



Project Title: Central Police Station Conservation and Revitalisation Project
 工程項目名稱: 中區警署保育及活化計劃

Environmental Permit No. : EP-408/2011
 環境許可證編號 : EP-408/2011

Figure 3: Trees within the Project Site Included Proposed Treatment and Photo Record of Tree

圖 3: 位於工地內的樹木包括樹木的建議處理方法及照片記錄

(This figure was prepared based on Figure 4.5 of the EIA report (AEIAR-162/2011))
 (本圖是根據環評報告 (AEIAR-162/2011) 圖 4.5 編制)