

Civil Engineering Department
The Government of the Hong Kong Special Administrative Region

Agreement No. CE 68/99

Infrastructure for Penny's Bay Development Engineering Design and Construction

**Decommissioning of Cheoy Lee Shipyard
At Penny's Bay**

**EIA Report (Final)
Volume 2—Appendices**

February 2002

Maunsell Consultants Asia Ltd.
in association with
Maunsell Geotechnical Services Ltd
Maunsell Environmental Management Consultants Ltd

TABLE OF CONTENTS

Appendix 4A	Action Levels for Soil Remediation
Appendix 4B	Elevated PID Readings of Soil Samples
Appendix 4C	Results of Groundwater Level Measurements
Appendix 4D	Groundwater Screening Criteria for Chemicals with Detectable Concentration
Appendix 4E	Details of Risk Assessment for Groundwater
Appendix 4F	Laboratory Results of Physical Tests for Soil Samples
Appendix 4G	Cleanup Targets for Soil Remediation
Appendix 4H	Soil Test Results of Site Investigation at CLS
Appendix 4I	Remedial Investigation / Remedial Alternatives Evaluation and Remedial Action Work Plan prepared by IEC
Appendix 5A	Performance of Thermal Desorption Unit
Appendix 5B	Calculation of Emission Rates
Appendix 5C	Sample Output Files for Air Dispersion Models
Appendix 8A	Habitats and Vegetation Recorded in the Assessment Areas During Surveys Conducted 1999-2001