



Existing parking lot

**Photomontage 1**  
View South from Parking Lot on Castle Peak Road

**Maunsell**  
茂盛(亞洲)工程顧問有限公司

Photomontage 1 -View South from Parking Lot on Castle Peak Road  
- San Tin (The Existing Condition)

SCALE	N.T.S.	DATE	NOV 2003	
CHECK	-	DRAWN	-	
JOB No.	95102	FIGURE No.	10.41	REV