


Maps reproduced with permission of The Director of Lands. (C) Hong Kong Government.

FILENAME: G:\env\project\23573\drawings\3-rd_EIA-V8\Figure\EX-Figure9-1.dgn



圖例
Legend :

- 受污染的探孔位置
Location of drillhole identified as contamination
- 補救工作的範圍(探孔7米內直徑)
Extent of remediation works (within 7m diameter circle around drillhole)

REV	DATE	BY	SUB	APP	DESCRIPTION
△	DEC2003	SW	FC	ST	EIA REPORT
△	NOV2003	SW	FC	ST	EIA REPORT
△	JUNE2003	SW	FC	ST	EIA REPORT
△	7MAR2003	SW	FC	ST	EIA REPORT (2ND DRAFT)
△	11OCT2002	SW	FC	ST	EIA REPORT (1ST DRAFT)

DESIGNED BY	SW
DRAWN BY	JF
CHECKED BY	FC
IN CHARGE	ST
DATE	5 DEC 2003

KCR New Railway Projects
新鐵路策劃

奧雅納工程顧問
Ove Arup & Partners Hong Kong Limited

ARUP

GSA-5100 九龍南環線環境影響評估
KOWLOON SOUTHERN LINK KSL GSA-5100
EIA & ASSOCIATED SERVICES

受土地污染的探孔位置
LOCATION OF DRILLHOLE OF CONTAMINATION

CADD FILENAME	CADD DATE
SCALE	N.T.S.
DRAWING NUMBER	FIGURE 圖 9-1
SHEET NO	STAGE CODE REV
	P E