

Contents

1	Introduction.....	1-1
1.1	Background	1-1
1.2	Objectives of This EIA Study	1-2
1.3	The Structure of This EIA Report	1-3
2	Project Information.....	2-1
2.1	Description of the Project	2-1
2.2	The Scope of the Project.....	2-2
2.3	Dock Operation	2-4
2.4	Consideration of Alternative Options and Methods for the Project.....	2-6
2.5	Construction Programme	2-7
2.6	Interfacing with Other Projects	2-7
3.	Water Quality Impact Assessment.....	3-1
3.1	Introduction.....	3-1
3.2	Environmental Legislation, Standards and Guidelines.....	3-2
3.3	Description of Environment	3-10
3.4	Water Sensitive Receivers	3-12
3.5	Baseline Environmental Conditions.....	3-13
3.6	Assessment Methodology	3-40
3.7	Impact Evaluation.....	3-45
3.8	Mitigation Measures	3-68
3.9	Residual Impacts.....	3-69
3.10	Environmental Monitoring and Audit Requirements.....	3-71
3.11	Conclusions.....	3-71
4	Waste Management	4-1
4.1	Introduction.....	4-1
4.2	Environmental Legislation, Standards and Guidelines.....	4-1
4.3	Assessment Methodology	4-4
4.4	Baseline Condition of Marine Sediment	4-5
4.5	Impact Evaluation.....	4-10
4.6	Mitigation Measures	4-12
4.7	Residual Impacts.....	4-13
4.8	Environmental Monitoring and Audit Requirements.....	4-13
4.9	Conclusions.....	4-13
5	Air Quality Impact Assessment During Operation at Tsing Yi	5-1
5.1	Introduction.....	5-1

5.2	Environmental Legislation, Policies, Plans, Standards and Criteria.....	5-1
5.3	Description of Environment	5-3
5.4	Assessment Methodology	5-4
5.5	Impact Evaluation.....	5-7
5.6	Mitigation Measures	5-9
5.7	Residual Impacts.....	5-9
5.8	Environmental Monitoring and Audit Requirements.....	5-9
5.9	Conclusion.....	5-9
6	Hazard Assessment For the Dock at Tsing Yi.....	6-1
6.1	Introduction.....	6-1
6.2	Description of Relocation Project	6-2
6.3	Assessment of Risk Incidents	6-9
6.4	Identification of Mitigation Measures.....	6-13
6.5	Conclusions and Recommendations.....	6-15
7	Potential Oil Spillage during the Operation Stage at Tsing Yi.....	7-1
7.1	Introduction.....	7-1
7.2	Environmental Legislation and Standards.....	7-1
7.3	Sensitive Receivers.....	7-1
7.4	Oil Spillage Sources	7-1
7.5	Historical Spillage Incidents	7-1
7.6	Oil Pollution Contingency Procedure	7-3
7.7	Potential Impact of Oil Spillage	7-3
7.8	Cumulative Impacts.....	7-4
7.9	Mitigation Measures	7-4
7.10	Residual Impacts.....	7-5
7.11	Conclusions.....	7-5
8	Conclusions and Recommendations.....	8-1
8.1	Water Quality.....	8-1
8.2	Waste Management	8-1
8.3	Air Quality.....	8-2
8.4	Hazard Assessment for the Dock at Tsing Yi.....	8-2
8.5	Oil Spillage during the Dock Operation at Tsing Yi	8-2
8.6	Environmental Outcome.....	8-3
8.7	Overall Conclusions	8-5
9	Implementation Schedule of the Recommended Mitigation Measures	9-1

Tables

Table 2-1	The Co-ordinates of the Proposed New Site	2-1
Table 3-1	Relevant WQOs at the North Western WCZ and the Western Buffer WCZ	3-3
Table 3-2	International Standards for Heavy Metals and Micro-Pollutants in Marine Environment	3-6
Table 3-3	Standards for Heavy Metals and Micro-pollutants Recommended for this EIA	3-6
Table 3-4	Standards for Effluents Discharged into the Marine Waters of Southern, Mirs Bay, Junk Bay, North Western, Eastern Buffer and Western Buffer Water Control Zones	3-8
Table 3-5	Discharge Limits Specified in the Discharge Licence for Dock Operations at Yam O Wan	3-9
Table 3-6	Sediment Quality Criteria for the Classification of Sediment	3-10
Table 3-7	Water Sensitive Receivers	3-13
Table 3-8	Requirements of Seawater Sample Analysis	3-15
Table 3-9	Requirements of Sediment Sample Analysis	3-16
Table 3-10	Elutriate Samples	3-17
Table 3-11	Requirements of Elutriate Sample Analysis	3-18
Table 3-12	Sediment Biological Screening Test	3-19
Table 3-13	The Mixture of Composite Sediment Sample for Biological Screening Test for Category M Sediment	3-19
Table 3-14	EPD Marine Water Quality Monitoring Data in Year 2004	3-22
Table 3-15	Marine Water Quality Results at Yam O Wan (Collection Date: 21 May 2005)	3-23
Table 3-16	Marine Water Quality Results at Yam O Wan (Collection Date: 4 June 2005)	3-24
Table 3-17	EPD Sediment Quality Monitoring Data in Years 2000-2004	3-26
Table 3-18	Sediment Quality Results at the Existing Site	3-28
Table 3-19	Number of Sediment Samples with Contaminants exceeding LCEL and UCEL at the Existing Site	3-29
Table 3-20	Sediment Quality Results at the Proposed Site	3-30
Table 3-21	Sediment at the Existing Site - Biological Test Results Summary	3-31
Table 3-22	Bioaccumulation Testing Results for the Existing Site and Available Assessment Criteria	3-33
Table 3-23	Concentration of Copper in Organism Tissue at Test Initiation and Termination	3-34
Table 3-24	Concentration of Zinc in Organism Tissue at Test Initiation and Termination	3-35
Table 3-25	Concentration of Silver in Organism Tissue at Test Initiation and Termination	3-35
Table 3-26	Concentration of Mercury in Organism Tissue at Test Initiation and Termination	3-36
Table 3-27	Bioaccumulation Potential of Selected Contaminant in Sediments Collected from the Existing Site	3-39
Table 3-28	Summary of Particle Size Distribution at the Existing Site	3-46
Table 3-29	Predicted SS Elevation Resulting from Dredging for Retrieval of Anchor Blocks at the Existing Site	3-48
Table 3-30	Summary Results of Elutriate Sample Analysis at the Existing Site	3-50
Table 3-31	Predicted Elevation of Dissolved Copper Level at the Existing Site	3-51
Table 3-32	Summary Results of Particle Size Distribution at the Proposed Site	3-54
Table 3-33	Predicted SS Elevation Resulting from Dredging and Backfilling at the Proposed Site	3-55
Table 3-34	Summary Results of Elutriate Sample Analysis at the Proposed Site	3-57
Table 3-35	Predicted Elevation of Dissolved Copper Level at the Proposed Site	3-57
Table 3-36	Limitations on Discharge of Effluent Arising form Domestic Sewage	3-59
Table 3-37	Domestic Effluent Characteristics	3-59
Table 3-38	Predicted SS Elevation Resulting from Domestic Wastewater Discharge at Tsing Yi Site during the Operation Stage	3-60

Table 3-39	Industrial Effluent Characteristics	3-64
Table 3-40	Model Predictions of Water Quality Impacts Resulting from Industrial Effluent Discharges at Tsing Yi during the Operation State	3-65
Table 3-41	Residual Water Quality Impact at the Existing Site during the Decommissioning Stage	3-70
Table 3-42	Residual Water Quality Impact at Tsing Yi during the Commissioning Stage	3-70
Table 3-43	Residual Water Quality Impact Resulting from the Domestic Wastewater Discharge from the Dock at Tsing Yi during the Operation Stage	3-70
Table 3-44	Residual Water Quality Impact Resulting from the Industrial Wastewater Discharge from the Dock at Tsing Yi during the Operation Stage	3-71
Table 4-1	Chemical Analysis Results of Marine Sediment at Yam O Wan and Reference Sediment	4-7
Table 4-2	The Mixture of Composite Sediment Sample for Biological Screening Test for Category M Sediment	4-8
Table 4-3	Biological Test Results Summary	4-8
Table 4-4	Chemical Analysis Results of Marine Sediment at Tsing Yi	4-10
Table 5-1	Hong Kong Air Quality Objectives	5-2
Table 5-2	Annual Averaged Concentration of SO ₂ and NO ₂ at Kwai Chung Air Quality Monitoring Station	5-3
Table 5-3	Representative Air Sensitivity Receiver	5-4
Table 5-4	Operation Details of the Generators of Floating Dock No. 3	5-5
Table 5-5	Operation Details of the Generators of Floating Dock No. 1	5-6
Table 5-6	Predicted SO ₂ Concentrations at nearby ASRs	5-8
Table 5-7	Predicted NO ₂ Concentrations at nearby ASRs	5-8
Table 6-1	Details of Anchoring Work before Relocation	6-5
Table 6-2	Details of Moving of Dock, Positioning and Mooring Work	6-6
Table 6-3	Details of Retrieval & Post-anchoring	6-6
Table 6-4	Temporal Distributions of Floating Dock Staff in Normal Working Days	6-9
Table 6-5	LPG Storage in EMWT and CT	6-10
Table 6-6	LPG Handling Facilities in EMWT and CT	6-10
Table 6-7	Identified LPG Risk Incidents	6-11
Table 6-8	The Closest Distance between the Terminal Facilities and the Dock	6-12
Table 9-1	Mitigation Measures Implementation Schedule	9-5

Figures

Figure 1-1	The Location of the Existing Floating Dock and Proposed New Site
Figure 2-1	The General Arrangement of the Existing Dock
Figure 2-2	The Locations of Existing Dock and Anchor Blocks
Figure 2-3	The Locations of Proposed Dock Site and Anchor Blocks and nearby Floating Docks
Figure 3-1	Locations of the North Western WCZ and Western Buffer WCZ
Figure 3-2	Depth Average Peak Velocities during a Typical Flood Tide in a Wet Season
Figure 3-3	Depth Average Peak Velocities during a Typical Ebb Tide in a Wet Season
Figure 3-4	The Locations of Major Pollution Sources at the Existing Site
Figure 3-5	The Locations of Major Pollution Sources at the Proposed Site
Figure 3-6	Locations of Adjacent Beaches
Figure 3-7	Locations of Adjacent Fish Culture Zones
Figure 3-8	EPD Water Quality Monitoring Stations
Figure 3-9	EPD Sediment Quality Monitoring Stations in Typhoon Shelters and Open Waters of Hong Kong
Figure 3-10	Sampling Locations at the Existing Site

Figure 3-11	Sampling Locations at the Proposed Site
Figure 3-12	Sampling Locations of Reference Sediment
Figure 3-13	The Sediment Classification of the Collection Sediment Samples at the Existing Site
Figure 3-14	The Sediment Classification of the Collection Sediment Samples at the Proposed Site
Figure 3-15	The Pit and the Anchor Block
Figure 3-16	The Discharge Points of the Dock
Figure 3-17	Schematic Design of the Settling Tank
Figure 3-18	The Design of Airlift Suction Dredge Rig
Figure 5-1	Location of Nearby Air Sensitive Receivers
Figure 5-2	Air Quality Impact Assessment Area
Figure 6-1	Relocation Process Flow Diagrams
Figure 6-2	Location of Yiu Lian Floating Dock No.3 at Tsing Yi

Appendices

Appendix 2A

Construction Programme

Appendix 3A

Literature Review on the Handling and Treatment Methods for Contaminated Sediment

Appendix 3B

Ship Receiving Procedure

Appendix 3C

Literature Review on the Characteristics and Potential Environmental Impacts of Non-TBT Antifouling Paints

Appendix 3D

Bioaccumulation Test Report

Appendix 3E

Illustration of the Dredging Process at the Existing Site

Appendix 3F

Water Quality Objectives for North Western Water Control Zone and Western Buffer Water Control Zone

Appendix 3G

Conceptual Design of Silt Curtain

Appendix 5A

Air Pollution Emission Rates

Appendix 5B

Air Quality Modelling Results

Appendix 6A

Evacuation Plan for Floating Dock No. 3

Appendix 7A

Oil Pollution Contingency Procedure