
Project: Proposed Development at Fung Lok	Location: Shing Uk	Ref # FLW-01
Wai	Tsuen	
Originally Recorded: 06/02/2001	Updated On: 24/04/200	7
Original Usage: Tsz Tong (Kwing Ling	Current Usage: Tsz Tong (Kwing Ling	
Tong)	Tong)	
Orientation: Southwest	Map Reference: N/A	
Construction Date: 1971	Ownership: Private	
Setting: At the front of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Modern structure	
Architectural Significance: Low	Cultural Significance: High	
Description: Concrete two storey structure w	ith single storey anney r	nom on the left side

Description: Concrete two storey structure with single storey annex room on the left side. Flat roof. Building is painted yellow with grey trim at the base. Balcony across the façade of the first floor.

Inscriptions: 廣陵堂




Location: Shing Uk Tsuen	Ref # FLW-02	
Updated On: 24/04/2007		
Current Usage: Storage		
Map Reference: N/A		
Ownership: Private		
Historical Associations: None		
Degree of Modification: Low		
Cultural Significance: Low		
and roof collapsed. Single r	oom in interior	
	Tsuen Updated On: 24/04/2007 Current Usage: Storage Map Reference: N/A Ownership: Private Historical Associations: N Degree of Modification: I	



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref# FLW-03
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: Northern end of second terrace row	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: End unit green brick courtyard terrace. Flat roof on the front and pitched tile roof on the main section. Decorative door hood with moulded frieze panel on the façade. Modern wooden door in wooden frame

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref# FLW-04	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007		
Original Usage: Residential	Current Usage: Abandoned		
Orientation: South	Map Reference: N/A		
Construction Date: Pre 1950	Ownership: Private		
Setting: Just outside the entrance to the village	Historical Associations: None		
Condition: Ruin	Degree of Modification:		
Architectural Significance: Low	Cultural Significance: Low		
Description: Ruins of a green brick building in	n several sections		
Inscriptions: None			
Additional Notes: None			



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref# FLW-05
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Fung Shui Tree Shrine	Current Usage: Fung Shui Tree Shrine	
Orientation: Southwest	Map Reference: N/A	
Construction Date: N/A	Ownership: Private	
Setting: At the entrance to the village	Historical Associations: None	
Condition: N/A	Degree of Modification:	
Architectural Significance: N/A	Cultural Significance: High	
Description: A large Banyan Tree		
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Ref # FLW-06 Tsuen	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Residential	
Orientation: Southwest	Map Reference: Between buildings 8 and 9	
Construction Date: Pre 1950	Ownership: Private	
Setting: In the front terrace row of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Moderate	
Architectural Significance: Low	Cultural Significance: Moderate	

Description: Row of five green brick courtyard style terrace units. The facades of all of the structures have been renovated. The corner unit at the left has green brick wall section and some stone foundation. Flat front roofs with pitched tile main roof and plain ridge. Brick projecting eaves at the rear wall.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen Ref # FLW-0	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: see additional notes	
Orientation: Southwest	Map Reference: #3 and 4	
Construction Date: Pre 1950	Ownership: Private	
Setting: In the front row of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Moderate	
Architectural Significance: Low	Cultural Significance: Moderate	

Description: Two green brick courtyard style units. Flat roof over the whole building. Modern doors and entranceways. Decorative moulding under the eaves of the façade with traces of paint. All windows are modern.

Inscriptions: None

Additional Notes: Building has been demolished as of the 2007 survey



Location: Shing Uk Tsuen	Ref # FLW-08
Updated On: 24/04/2007	
Current Usage: Closed up	
Map Reference: #2	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
	Tsuen Updated On: 24/04/2007 Current Usage: Closed up Map Reference: #2 Ownership: Private Historical Associations: N Degree of Modification: L

Description: Green brick courtyard terrace style unit with flat front roof and pitched tile main roof with plain ridge. Decorative door hood and frieze panels across the façade and sides of the building. Concave moulding on the rear of the building under the eaves. Modern metal door/ gate in modern frame.

Inscriptions: None



Tsuen	
Updated On: 24/04/2007	
Current Usage: Closed up	
Map Reference: #1	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	

Description: Courtyard terrace style unit, pounded earth walls with render covering. Flat front roof and pitched tile main roof with plain ridge. Wooden door in modern frame. Plain frieze panels on the building with concave moulding on the rear of the building. Windows in metal frames have been added to the side and rear of the building.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref# FLW-10
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Southwest	Map Reference: #26, 27 and 28	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the southeastern corner of the village	Historical Associations: None	
Condition: #26 (ruin) #27 and 28 (poor)	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: Green brick courtyard terrace structures with flat front roofs and pitched main tile roof with plain ridge. All have double panel wooden doors with cut granite lintels and threshold stones. Each unit has a decorative door hood. Windows have been added to the rear of the building. Concave moulding under the eaves on the rear of the building.


Inscriptions: None



Location: Shing Uk Tsuen Ref # FLW-11	
Updated On: 24/04/2007	
Current Usage: Closed up/ but may be occupied	
Map Reference: #23, 24 and 25	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Moderate	

Description: Three green brick courtyard style units, two mid and one end. Flat front roofs with pitched tile main roof with plain ridge. Decorative door hoods on all units with decorated frieze panel across the façade. Double panel wooden doors with cut granite threshold stones and lintels.


Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref # FLW-12
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Southwest	Map Reference: #19, 19A, 20	
Construction Date: Pre 1950	Ownership: Private	
Setting: Middle section of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: Four green brick courtyard terrace style units with flat front roofs on three units and collapsed slanted roof on one and pitched tile main roofs. Double panel wooden doors with cut granite lintels and threshold stones. Course of cut granite along the bottom of the structure. Each unit has a decorative door hood and there are decorated frieze panels across the façade.


Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref # FLW-13
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Residential	
Orientation: Southwest	Map Reference: #15	
Construction Date: Pre 1950	Ownership: Private	
Setting: Middle section of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: End unit green brick courtyard terrace with flat front roof and pitched tile main roof with plain ridge. Decorative door hood and frieze panel on the façade. Cut granite door frame and lintel with modern metal gate.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	ef# FLW-14
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up/ Abandoned	
Orientation: Southwest	Map Reference: Beside #32	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Poor and ruin	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	
D. 14 M. 111		

Description: Two green brick courtyard style units. Plain frieze panels on the façade and decorative door hoods over each of the entrances. One unit has wooden door and wooden gate in half frame. The door is missing on the other structure.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen Ref # FLW-15	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: see Additional Notes	
Orientation: Southwest	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the northwestern edge of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Rectangular brick shed with pitched tile roof. Plain brickwork with no decorative features.

Inscriptions: None

Additional Notes: There was originally a large ruinous structure in front of this building that was included as the same number in the original survey.



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref # FLW-16
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: 1 unit (residential) 2 units(abandoned)	
Orientation: Southwest	Map Reference:	
Construction Date: Pre 1950	Ownership: Private	
Setting: Back central section of the village	Historical Associations: None	
Condition: 1 (Good); 2(ruins)	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	7
Description: Three green brick courtyard terr hoods over the entrances and stone thresholds closed up unit. Modern gate on the closed up u	. Tile and concrete roof with	orative door I plain ridge over
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref # FLW-17
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	7
Original Usage: Shed	Current Usage: Closed up	
Orientation: Southwest	Map Reference: Beside #30	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen Ref # FLW-18	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Ancestral Hall	Current Usage: Ancestral Hall	
Orientation: Southwest	Map Reference: Beside #30	
Construction Date: Modern Rebuilt	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance: Low	Cultural Significance: High	
Description: Modern concrete two storey struc	eture.	
Inscriptions: 盛家祠		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen Ref # FLW-1	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Abandoned	
Orientation: Southwest	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the southeastern section of the village	Historical Associations: None	
Condition: Ruins	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Two green brick courtyard style terrace units, walls intact roof partially collapsed. Stone foundation. Decorative door hoods over the entrances and frieze panels on façade. Heavily overgrown.

Inscriptions: None



19 in foreground and 20 façade in the right hand side of the picture

Location: Shing Uk Tsuen	Ref # FLW-20
Updated On: 24/04/2007	
Current Usage: Abandoned	
Map Reference: N/A	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
	Tsuen Updated On: 24/04/2007 Current Usage: Abandoned Map Reference: N/A Ownership: Private Historical Associations: Non

Description: Green brick courtyard style terrace units with flat front roof and pitched tile main ridge. Decorative door hood above the entrance and frieze panels. Cut granite threshold stone, wooden door and frame. Back sections of the buildings are gone.

Inscriptions: None




View of the ruins of #20 from the back in the foregroun

Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref# FLW-21
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Southwest	Map Reference: #39 to 43	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the back of the village (southwestern edge)	Historical Associations: None	
Condition: Good	Degree of Modification: Low (three of the units have modern doors)	
Architectural Significance: High	Cultural Significance: High	


Description: Five green brick terrace units. Flat roofs over the front courtyard sections and tile roof over the main section with plain ridge. Some units have stone thresholds and lintels. Decorative door hoods over the entrances. Mixture of modern and traditional doors and gates.


Inscriptions: None

Additional Notes: Complete row with no modern structures in it, as an intact terrace row (which is very rare) the architectural and cultural significance has been rated as high.



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen Ref # FLW-22	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Unknown/ possibly residential	Current Usage: Abandoned	
Orientation: Southwest	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the back of the village behind animal pens	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Narrow rectangular building and lintel in the main building. Annex section has a		
Inscriptions: None		
Additional Notes: None		






Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref# FLW-23
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Animal pens	Current Usage: Abandoned	
Orientation: Southwest	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: At the back of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Moderate	
Architectural Significance: Low	Cultural Significance: Low	

has been reconstructed and is modern. The roofs are overgrown with vegetation.


Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Shing Uk Tsuen	Ref # FLW-24
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Southwest	Map Reference: #35 and 36	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the back central section of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Moderate	

Description: Two green brick courtyard terrace style units. Cut granite lintels and threshold stones. Decorative door hood over the entrances of each unit and decorative frieze panels along the facade. Flat roofs over the front sections and pitched tile roof with plain ridge over the main section.

Inscriptions: None



Location: Shing Uk Tsuen	Ref# FLW-25
Updated On: 24/04/200	7
Current Usage: see additional notes	
Map Reference: N/A	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
	Tsuen Updated On: 24/04/200 Current Usage: see add Map Reference: N/A Ownership: Private Historical Associations: Degree of Modification:

Description: Green brick and uncut stone building. Courtyard style with only the front section remaining. Tile and concrete roof. Cut granite threshold stone. Decorative door hood over the entrance. Structure to the rear is completely overgrown

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref# FLW-26
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Shrine	Current Usage: Shrine	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: At the front of the village, northeastern corner	Historical Associations: None	
Condition: Good	Degree of Modification: Moderate	
Architectural Significance: Moderate	Cultural Significance: High	

Description: Concrete shrine with traditional decorative features, including wok yee style gables and curling end ridge (on the back wall). Rectangular shaped enclosure on a rounded shaped platform. Lion statue decorations on the inner and outer enclosure.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-27	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Village Gate	Current Usage: Village Gate	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the cente front of the village	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance: Moderate	Cultural Significance: High	
D. J. d. T. Hall J.		

Description: Traditional style brick village gate, single room inside with small shrine. Rectangular entrance on the front and rounded opening at the back. Façade has painted frieze under a modern tile parapet/ There are two round ventilation opening under the frieze on the façade. Wooden loft and rafters inside.


Inscriptions: 大井圍



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLV	V-28
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the front row of the village at the southeastern corner.	Historical Associations: None	
Condition: Poor	Degree of Modification:	
Architectural Significance: Low	Cultural Significance: Moderate	
Description: Rectangular shaped end unit wit door and windows.	n tile pitched roof and plain ridge. Moder	'n
Inscriptions: None		
Additional Notes: None		




Location: Tai Tseng Wai	Ref # FLW-29
Updated On: 24/04/2007	I
Current Usage: Gate	
Map Reference: N/A	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
brick frame (no door or ga	ite attached)
	Wai Updated On: 24/04/2007 Current Usage: Gate Map Reference: N/A Ownership: Private Historical Associations: N Degree of Modification: L Cultural Significance: Lo



Location: Tai Tseng Wai	Ref # FLW-30
Updated On: 24/04/2007	
Current Usage: Closed up	
Map Reference: Beside #61	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
	Wai Updated On: 24/04/2007 Current Usage: Closed u Map Reference: Beside # Ownership: Private Historical Associations: I Degree of Modification: I

Description: Three green brick courtyard terrace units. Flat roof over the front courtyard sections. Decorative door hoods on both units and frieze panels (decoration has faded). Double panel wooden doors with left hand unit having a cut granite lintel and half door frame. This unit also has a cut granite corner stone.


Inscriptions: None



Location: Tai Tseng Wai Ref # FLW-31	
Updated On: 24/04/2007	
Current Usage: Empty apart from shrine	
Map Reference: #56	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	

Description: Green brick courtyard style unit with flat roof over the front courtyard section and tile pitched roof over the main section with plain ridge. Decorative door hood and frieze panel on the façade.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-32	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: #54	
Construction Date: Pre 1950	Ownership: Private	
Setting: To the south of the main village in an area with approximately 7 other units.	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Green brick and pounded earth of exterior. Rear wall brick.	courtyard terrace unit covered in render on	
Inscriptions: None Courtyard style unit with e	exterior completely covered in render.	
Additional Notes: None		



Location: Tai Tseng Wai	Ref # FLW-33
Updated On: 24/04/2007	<u> </u>
Current Usage: Closed up	
Map Reference: N/A	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
	Wai Updated On: 24/04/2007 Current Usage: Closed up Map Reference: N/A Ownership: Private Historical Associations: N Degree of Modification: L


Description: Green brick courtyard style unit in between two modern units. Façade has been painted white. Decorative door hood and frieze panels on the façade. Wooden door and frame. Cut granite corner stone. Flat roof over the front section and pitched tile roof over the main section.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-34
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the southern central section of the village	Historical Associations: None	
Condition: Poor	Degree of Modification:	
Architectural Significance: Moderate	Cultural Significance: Low	
Description: Green brick courtyard terrace en lintel door and door frame. Tile roof pitched o courtyard section.	d unit. Decorative door ho over main section. Flat roof	od with wooden over front

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-35	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: #50 and 51	
Construction Date: Pre 1950	Ownership: Private	
Setting: To the south of the main village in an area with approximately 7 other units.	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: Two green brick courtyard style units with flat roof and balustrade (green ceramic balusters in concrete frame) added to the front courtyard sections. Pitched tile main roof with plain ridge. Third unit to the side. Double panel wooden doors with cut granite lintels and thresholds.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-36
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Unknown	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: Beside #70	
Construction Date: Unknown	Ownership: Private	
Setting: Back central section of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Section of brick walls only remain	ning historical section.	
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-37	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: Behind #74	
Construction Date: Pre 1950	Ownership: Private	
Setting: Back southwestern section of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Green brick mid terrace unit . Washing over front.	ooden door in wooden frame with modern	
Inscriptions: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-38	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: #60	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the back of the village, last terrace row	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Two green brick courtyard style partially collapsed. Decorative door hood over	units front walls are intact, rear walls have rone of the units entrances.	
Inscriptions: None		
Additional Notes: None		




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-39	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Village God's Hall	Current Usage: Village God's Hall	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: Centre of the back terrace row of the village, aligned with entrance gate	Historical Associations: None	
Condition: Good	Degree of Modification: Moderate	
Architectural Significance: Low	Cultural Significance: High	
Description: Modern rebuilt gods hall, red tile Single hall.	e façade tile roof with green ceramic ridge.	
Inscriptions: 大井圍神廳		
Additional Notes: None		




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-40
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Yee Hing Tong Study Hall	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: Beside #18	
Construction Date: Pre 1950	Ownership: Cheng Clan	
Setting: At the back northwestern corner of the village	Historical Associations: None	
Condition: Poor to ruin	Degree of Modification: Low	
Architectural Significance: High	Cultural Significance: High	

Description: Green brick main hall with back annexes in ruinous condition. Painted frieze panel on the façade with inscription over the doorway. Wooden shuttered window on the façade. Modern roof.


Inscriptions: 義慶堂



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-41
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: #18	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the back of the village, northwestern corner	Historical Associations: None	
Condition: Poor to ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Brick rectangular structure next on façade. No decorative features. Tile and co		door and window
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-42	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: #47	
Construction Date: Pre 1950	Ownership: Private	
Setting: Back central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description:		
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-43
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	I
Original Usage: Residential	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: Beside #19	
Construction Date: Pre 1950	Ownership: Private	
Setting: Back central section of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description:		III WIII WALLES OF THE STATE OF
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-44
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	7
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: #24, 25 and 26	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Poor	Degree of Modification:	
Architectural Significance: Low	Cultural Significance: Low	

Description: Three brick terrace structures all have wooden doors in wooden door frames, one cut granite threshold stone remaining. Right hand unit has render covering on the façade, other to have brick, eroding away in places. No decorative features.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Ref # FLW-45 Wai	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Residential/ closed up	
Orientation: Northeast	Map Reference: #18	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village.	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Two mid green brick terrace units with pitched tile roof. Façade walls have been whitewashed. Double panel wooden doors and frame. Plain construction with no decorative features. Window air con added to rear wall.


Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-46
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Abandoned or vacant	
Orientation: Northeast	Map Reference: #41, 41a and 43	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good to poor	Degree of Modification: Low	
Architectural Significance: High (as the entire row is intact)	Cultural Significance: Moderate	

Description: Five green brick courtyard style terrace units with concrete covered or stone foundations. Single pitched tile roof over the main sections and flat roofs over the front. Moulding under the eaves on the facade. Mixture of modern doors and traditional.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-47	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Residential	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Architectural Significance: Low Description: Green brick structure with pitch Wooden door in wooden frame. No decorative	ed tile roof. Rough cut stone foundation.	

Inscriptions: None



Location: Tai Tseng Wai Ref # FLW	
Updated On: 24/04/2007	
Current Usage: Abandoned	
Map Reference: N/A	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	

Description: Ruins of three structures with some green brick wall sections remaining and very overgrown with vegetation.


Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-49
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: #46	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central part of the village.	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Green brick courtyard style terrace unit with stone foundation. Pitched tile roof over main section and flat roof over the front. Modern door and gate on the entrance. No decorative features. Exterior has been painted pink.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Ref # FLW-50	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: On the Northeastern edge of the village facing into the village.	Historical Associations: None	
Condition: Poor to ruin	Degree of Modification:	
Architectural Significance:	Cultural Significance:	
Description: Small terraced unit with mixture pounded earth) and pitched tile roof, partially		
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-51	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: On the northeastern edge of the village outer row facing into the village.	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Two green brick walls on uncut s	stone foundation, only small section of roof.	

Description: Two green brick walls on uncut stone foundation, only small section of roof. Double panel wooden door in wooden frame and also one metal gate. Pitched tile roof. No decorative features.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-52	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up/ storage	
Orientation: Northeast	Map Reference: #9	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central part of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Green brick courtyard style end section, flat roof on the front. Double panel wo features.		
Inscriptions: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Ref # FLW-53 Wai	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: (see Additional Notes)	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: Near the back of the village	Historical Associations: None	
Condition: Ruins	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Brick wall sections with stone foundations with interior wall sections of mud brick. Entrance way still discernable with brick doorstep.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-54
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential?	Current Usage: Abandoned	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Some brick and mud brick walls remaining features.	and sections of collapsed re	oof are only



Location: Tai Tseng Wai	Ref # FLW-55
Updated On: 24/04/2007	
Current Usage: Closed up	
Map Reference: #8	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	
	Wai Updated On: 24/04/2007 Current Usage: Closed up Map Reference: #8 Ownership: Private Historical Associations: N Degree of Modification: L

Description: Green brick courtyard style mid terrace unit. Pitched tile roof over main section and flat roof over the front courtyard section. Uncut stone foundations on the faced and rear walls. Window has been added in the rear wall.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-56
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Storage	
Orientation: Northeast	Map Reference: #33	
Construction Date: Pre 1950	Ownership: Private	
Setting: Near the back of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Green brick walls with stone four beams in very poor condition. Vegetation grow		
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-57
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	<u> </u>
Original Usage: Residential	Current Usage: Residential/ storage (close up)	
Orientation: Northeast	Map Reference: # 34	
Construction Date: Pre 1950	Ownership: Private	
Setting: Near the back of the village	Historical Associations: None	
Condition: Poor	Degree of Modification: Moderate	
Architectural Significance: Low	Cultural Significance: Low	
Description: Brick courtyard style terrace uni No decorative features.	t with pitched main roof ar	nd flat front roof.
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-58
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Residential	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Pre 1950	Ownership: Private	
Setting: Near the back of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Brick end terrace unit. No decora	ative features. Tile roof.	
Inscriptions: None		
Additional Notes: None		




Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai Ref # FLW-59	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Vacant/ Abandoned	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: Near the back of the village	Historical Associations: None	
Condition: Poor to ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Structure made of a mixture of d partially collapsed. Foundation is made of rub	TO THE PARTY OF TH	
Inscriptions: None		



Location: Tai Tseng Ref # FLW-60	
Updated On: 24/04/2007	
Current Usage: Vacant/ Closed up	
Map Reference: N/A	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	

Description: Three green brick (and pounded earth walls) courtyard terraced units, one end unit and one mid unit. One unit has sandstone foundation and the other has stone foundation. Pitched tile roofs on main sections and flat roofs on front.


Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Wai	Ref # FLW-61
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Unknown	Current Usage: Abandon	ed
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: Front central section of the village	Historical Associations: N	lone
Condition: Ruin	Degree of Modification:	
Architectural Significance: Low	Cultural Significance: Low	
Description: Section of brick walls only remain	ning feature.	e recent de la constant de la consta
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Tai Tseng Ref # FLW-62 Wai	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Vacant/ Closed up	
Orientation: Northeast	Map Reference: #30 to 32	
Construction Date: Pre 1950	Ownership: Private	
Setting: Near the back of the village	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance: Moderate	Cultural Significance: Moderate	
Description: Three green brick courtyard terr on façade. Pitched tile roofs on main section, f added in two of the units rear walls. Inscriptions: None	race units. Central unit has render covering lat roofs on the front. Windows have been	




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-63	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Tin Hau Temple	Current Usage: Tin Hau Temple	
Orientation: South southwest	Map Reference: N/A	
Construction Date: Rebuilt in 1981	Ownership: Private	
Setting: To the west of the village in an open area	Historical Associations: None	
Condition: Good	Degree of Modification: High	
Architectural Significance: Moderate	Cultural Significance: High	
Description: Two halls with central courtward	Tiles in red brick style on the exterior	

Description: Two halls with central courtyard. Tiles in red brick style on the exterior. Green ceramic decorative ridge. Decorative frieze panels on the façade under the eaves.

Inscriptions: 天后古廟

Additional Notes: The temple is shared by all three of the villages.



Project: Proposed Development at Fung Lok Wai	Location: Near Ng Uk Tsuen	Ref # FLW-64
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Shrine	Current Usage: Shrine	
Orientation: Northeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: Along the path between Ng Uk Tsuen and the Tin Hau Temple	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: High	
Description: Large Banyan tree with three wo	oden slats in a rectangle pla	aced in front.
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-65	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #85	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the back of the village	Historical Associations: None	
Condition: Poor	Degree of Modification:	
Architectural Significance: Low	Cultural Significance: Low	

Description: Green brick and pounded earth courtyard style building. Brick on the façade and render covered pounded earth on the side. Flat roof on the front section and pitched tile roof on the main section. Decorative door hood over entrance.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-66	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #67 and 68	
Construction Date: Pre 1950	Ownership: Private	
Setting: On the western edge of the village, not in a terrace row	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Moderate	
Description: Two units with side annex. Pitche earth walls. Piers at centre and on ends of the capitals only decorative feature.	ed tile roof and green brick and pounded façade, moulded decoration on the pier	




Inscriptions: None


Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # F	LW-67
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Abandoned	
Orientation: South southwest	Map Reference: Behind #76	
Construction Date:	Ownership: Private	
Setting: At the back of the village	Historical Associations: None	
Condition: Ruins	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Two Green brick façade walls wi inner wall sections. Wooden door frames. Doo		rth
Inscriptions: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-68
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	7
Original Usage: Residential	Current Usage: Abandoned	
Orientation: South southwest	Map Reference: Behind #74	
Construction Date: Unknown	Ownership: Private	
Setting: At the back of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Green brick and pounded earth of collapsed. Walls of main unit mostly intact but		nt section wall
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-69
Originally Recorded: 06/02/2001	Updated On: 24/04/200	7
Original Usag <mark>e:</mark> Unknown	Current Usage: Abandoned	
Orientation: South southwest	Map Reference: Beside #83	
Construction Date: Unknown	Ownership: Private	
Setting: At the back of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Green brick and pounded earth decoration in good shape. No door or roof.	 façade with decorative do	oor hood, painted
Inscriptions: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-70
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Unknown	Current Usage: Abandoned	
Orientation: South southwest	Map Reference: Beside #72	
Construction Date: Unknown	Ownership: Private	
Setting: At the back of the village (second to last row)	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Section of brick wall and collapse	ed pounded earth section.	
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-71	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Vacant	
Orientation: South southwest	Map Reference: #69	
Construction Date: Pre 1950	Ownership: Private	
Setting: To the east of the main village at the back	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Green brick courtyard style unit with modern flat roof on front and added middle section on roof with access to front roof area. Pitched tile main roof. Decorative door hood and frieze panels on the front courtyard section.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-72	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: Behind #69	
Construction Date: Pre 1950	Ownership: Private	
Setting: To the east of the main village at the back	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Small single room pounded earth Modern door and windows.	and render covered shed. Pitched tile roof.	
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-73
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Unknown	Current Usage: Abandoned	
Orientation: South southwest	Map Reference: #76	
Construction Date: Unknown	Ownership: Private	
Setting: At the back of the village (second to last row)	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Brick courtyard style terrace uni panels on the façade. No roof over the front se		od and frieze
Inscriptions: None		
Additional Notes: Were two units during the 2	2001 survey	



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-74	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Unknown	Current Usage: Abandoned	
Orientation: South southwest	Map Reference: In front of #79-80	
Construction Date: Unknown	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Ruin	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	
Description: Lower sections of brick walls.	,	
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-75	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #67 and 68	
Construction Date: Pre 1950	Ownership: Private	
Setting: On the western edge of the village, not in a terrace row	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Moderate	
D	1.00	

Description: Two units with side annex. Pitched tile roof and green brick and pounded earth walls. Piers at centre and on ends of the façade, moulded decoration on the pier capitals only decorative feature.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-76
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Study Hall	Current Usage: Study Hall	
Orientation: South southwest	Map Reference: #77	
Construction Date: Unknown	Ownership: Private	
Setting: At the back of the village (second to last row)	Historical Associations: None	
Condition: Good	Degree of Modification: High	
Architectural Significance: Low	Cultural Significance: High	
Description: Modern two storey terrace struc	ture with tile facade, balcon	ny on first floor

Description: Modern two storey terrace structure with tile façade, balcony on first floor.

Inscriptions: 國祥書室


Additional Notes: Originally called the Sam Shue Tong 三書堂, name changed about 15 years ago to "Kwok Cheung Study Hall" after ancestor of the village



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-77
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #61 to 64	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good to poor	Degree of Modification: Moderate	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: Four green brick courtyard style units, three have traditional decorative door hoods and one has a modern parapet (Plain). Flat roofs over the front sections and pitched tile roof over the main section.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-78	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #57 to 59	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Moderate	Cultural Significance: Low	


Description: Row of three green brick courtyard style units. Double panel wooden doors. Decorative door hoods over the entrances with some sections of decorative frieze panels intact.

Inscriptions: None

Additional Notes: Were four units in 2001 survey.



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-79
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Tsz Tong	Current Usage: Tsz Tong	
Orientation: South southwest	Map Reference: #35	
Construction Date: Unknown	Ownership: Private	
Setting: Eastern side of the village, middle terrace row	Historical Associations: None	
Condition: Good	Degree of Modification: High	
Architectural Significance: Low	Cultural Significance: High	
Description: Modern two storey village terrac first floor.	e structure. Tile façade w	ith balcony on the
Inscriptions: 永益堂		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Ref # FLW-80	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #36 and 37	
Construction Date: Pre 1950	Ownership: Private	
Setting: Central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Moderate	
Architectural Significance: Moderate	Cultural Significance: Low	

Description: Four green brick courtyard terrace units. One with traditional façade and door hoods. One has modern door frame with traditional decorative door hood. One has modified façade and the last is a green brick façade with no decorative features in ruinous condition.

Inscriptions: None



Location: Ng Uk Tsuen Ref # FLW-	
Updated On: 24/04/2007	
Current Usage: Closed up	
Map Reference: #44	
Ownership: Private	
Historical Associations: None	
Degree of Modification: Low	
Cultural Significance: Low	

Description: Green brick façade with no roof over front courtyard section. Main section has pitched tile roof with plain ridge. Decorative door good over the entrance and plain frieze panels on façade.

Inscriptions: None




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-82	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Well	Current Usage: Not in use	
Orientation: South southwest	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: To the southwest of the village	Historical Associations: None	
Condition: Good	Degree of Modification: Moderate	
Architectural Significance: Low	Cultural Significance: High	
Description: Well enclosure has been covered holder.	in concrete. Small shrine with incense	
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Ref # FLW-83	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Closed up	
Orientation: South southwest	Map Reference: #30	
Construction Date: Pre 1950	Ownership: Private	
Setting: Front central section of the village	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance: Low	Cultural Significance: Low	
Architectural Significance, Low	Cultural Significance: Low	

Description: Two green brick courtyard terrace style structures. Modern parapet across the front with 1972 renovation date. Double panel wooden door on one unit and modern gate on the other unit.


Inscriptions: "1972" on parapet



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-84
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	7
Original Usage: Residential	Current Usage:	
Orientation: South southwest	Map Reference: #26 and 25	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the southeastern (front section) of the main village	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance: Moderate	Cultural Significance: Moderate	

Description: Two green brick courtyard style terrace mid units. Both units have decorative door hoods with moulded and painted decoration and cut granite thresholds with traditional wooden doors in wooden frames. Frieze panels are present under the eaves on the façade but the decoration has faded.


Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-85
Originally Recorded: 06/02/2001	Updated On: 24/04/20	007
Original Usage: Residential	Current Usage: Residential / vacant/ storage	
Orientation: South southwest	Map Reference: Behind row 7 to 10	
Construction Date: According to local informants they were built during the Japanese Occupation as village housing	Ownership: Private	
Setting: At the back of the southeastern end of the village, away from the main village.	Historical Association	s: None
Condition: Poor to good	Degree of Modification: Low to moderate	
Architectural Significance: Low	Cultural Significance: Moderate	
Description: Two small terraced units constru Single story with pitched roofs. No decorative		en brick mixture.
Inscriptions: None		
Additional Notes: None		




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-86
Originally Recorded: 06/02/2001	Updated On: 24/04/2	0007
Original Usage: Residential	Current Usage: Residential / vacant storage	
Orientation: South southwest	Map Reference: Behind row 7 to 10	
Construction Date: According to local informants the small units were built during the Japanese Occupation as village housing	Ownership: Private	
Setting: At the back of the southeastern end of the village, away from the main village.	Historical Associatio	ns: None
Condition: Poor to ruin	Degree of Modification: Low to moderate	
Architectural Significance: Low	Cultural Significance: Moderate	
Description: Two storey green brick end unit wi	th flat roof nad section	of ruin beside.
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-87	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Residential	Current Usage: Storage/ closed up	
Orientation: Southwest	Map Reference: Between 8 and 9	
Construction Date: Pre 1950	Ownership: Private	
Setting: At the southeastern side of the village near the entrance gate.	Historical Associations: None	
Condition: Poor	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Green brick mid terrace unit pitched roof (with vegetation growth). Cut granite at façade foundation and at sides of the doorway. Two small rectangular openings on the façade. No decorative features.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-88
Originally Recorded: 06/02/2001	Updated On: 24/04/20	007
Original Usage: Village gate	Current Usage: Village gate	
Orientation: South	Map Reference: Beside # 5-6	
Construction Date: Unknown	Ownership: Private	
Setting: At the southeastern section of the village away from the main section.	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance: High (rare for a gate to be freestanding)	Cultural Significance: High	

Description: Detached entrance gate of green brick. Tile and chunam pitched roof with plain ridge. Rectangular entrance on front and brick arch on rear entrance. Single room with storage area above.

Inscriptions: None

Additional Notes: The gate faces south south east whilst the majority of the village structures face South southwest.




Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-89
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	7
Original Usage: Shrine	Current Usage: Shrine	
Orientation: South southwest	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: To the southeast of the village, currently located in a paved car park village entry area.	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: High	
Description: Consists of small stones set in con	 	se holder.
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-90
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	L
Original Usage: Shrine	Current Usage: Shrine	
Orientation: South southwest	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: To the southeast of the village	Historical Associations: None	
Condition: Good	Degree of Modification:	
Architectural Significance:	Cultural Significance:	

Description: Green brick shrine with wok yee style gable sides and decorative ridge on back wall. Cut granite base and corner stones. Triangular stone set in frame in the centre of the back wall. Cut granite incense holder.

Inscriptions: None



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-91
Originally Recorded: 06/02/2001	Updated On: 24/04/20	007
Original Usage: School	Current Usage: Abandoned (and see additional notes)	
Orientation: South southeast	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: To the southeast of the village in a wooded area.	Historical Associations: None	
Condition: Poor	Degree of Modification:	
Architectural Significance:	Cultural Significance:	

Description: Rectangular concrete structure with recessed entrance on façade. Single story with flat roof. Stepped parapet on the façade with inscription of the school name. The southwestern wing of the school building has been replaced with a modern structure as of the 2007 survey.

Inscriptions: 公立 金仁學校

Additional Notes: Kam Yan Public School



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen	Ref # FLW-92
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Shrine	Current Usage:	
Orientation: South southwest	Map Reference: N/A	
Construction Date: Unknown	Ownership: Private	
Setting: At the southwestern edge of the village.	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: High	
Description: Building stones and moulded blo no decorative features.	cks with concrete incense	holder. Plain with
Inscriptions: None		
Additional Notes: None		



Project: Proposed Development at Fung Lok Wai	Location: Ng Uk Tsuen Ref # FLW-93	
Originally Recorded: 06/02/2001	Updated On: 24/04/2007	
Original Usage: Shed/ possibly residential	Current Usage: Storage	
Orientation: North	Map Reference:	
Construction Date: Pre 1950	Ownership: Private	
Setting: To the east of the main village near the front.	Historical Associations: None	
Condition: Good	Degree of Modification: Low	
Architectural Significance: Low	Cultural Significance: Low	

Description: Grey brick rectangular structure with uncut stone foundation. Pitched tile roof. Double panel wooden door. No decorative features.

Inscriptions: None

