

Civil Engineering and Development  
Department

**Pier Improvement at Lai Chi Wo**

Environmental Impact Assessment  
Report

262145/REP/011/LCW/3/01

This report takes into account the particular  
instructions and requirements of our client.

It is not intended for and should not be relied  
upon by any third party and no responsibility  
is undertaken to any third party.

Job number 262145

**Ove Arup & Partners Ltd**  
Level 5 Festival Walk  
80 Tat Chee Avenue  
Kowloon Tong  
Kowloon  
Hong Kong  
[www.arup.com](http://www.arup.com)

**ARUP**

## Contents

---

	Page
<b>1 Introduction</b>	<b>1-1</b>
<b>2 Project Description</b>	<b>2-1</b>
<b>3 Air Quality</b>	<b>3-1</b>
<b>4 Noise</b>	<b>4-1</b>
<b>5 Water Quality</b>	<b>5-1</b>
<b>6 Waste Management Implications</b>	<b>6-1</b>
<b>7 Land Contamination</b>	<b>7-1</b>
<b>8 Ecological Impact Assessment</b>	<b>8-1</b>
<b>9 Landscape and Visual Impact</b>	<b>9-1</b>
<b>10 Fisheries</b>	<b>10-1</b>
<b>11 Cultural Heritage</b>	<b>11-1</b>
<b>12 Environmental Monitoring and Auditing Requirements</b>	<b>12-1</b>
<b>13 Summary of Environmental Outcomes</b>	<b>13-1</b>
<b>14 Conclusion</b>	<b>14-1</b>

### Figures

<b>Figure 1.1</b>	<u>Location of Project (Lai Chi Wo)</u>
<b>Figure 1.2</b>	<u>Photo of the Existing Lai Chi Wo Pier</u>
<b>Figure 1.3</b>	<u>Layout of Project</u>
<b>Figure 3.1</b>	<u>Locations of Representative Air Sensitive Receivers and Concerned PATH Grids</u>
<b>Figure 4.1</b>	<u>Locations of Representative Noise Sensitive Receivers</u>
<b>Figure 5.1</b>	<u>Locations of Assessment Area, Representative Water Sensitive Receivers and EPD Monitoring Stations</u>
<b>Figure 5.2</b>	<u>Landforms of Lai Chi Wo and Coastal Crooked Harbour</u>
<b>Figure 5.3</b>	<u>Hydrographic Survey</u>
<b>Figure 5.4</b>	<u>Comparison of Proposed Lai Chi Wo Pier and Sai Kung Public Pier</u>
<b>Figure 6.1</b>	<u>Proposed Works Area and Sediment Sampling Locations</u>
<b>Figure 8.1</b>	<u>Recognized Sites of Conservation Importance</u>
<b>Figure 8.2</b>	<u>Ecological Survey Locations within the 500m Assessment Area of Lai Chi Wo</u>
<b>Figure 8.3a</b>	<u>Habitat Map and Locations of Species of Conservation Importance</u>
<b>Figure 8.3b</b>	<u>Habitat Map and Locations of Species of Conservation Importance (Zoom-in to the Project)</u>

<b><u>Figure 8.4a</u></b>	<u>Photos of Habitats and Selected Species of Conservation Importance – Sheet 1 of 3</u>
<b><u>Figure 8.4b</u></b>	<u>Photos of Habitats and Selected Species of Conservation Importance – Sheet 2 of 3</u>
<b><u>Figure 8.4c</u></b>	<u>Photos of Habitats and Selected Species of Conservation Importance – Sheet 3 of 3</u>
<b><u>Figure 9.1a</u></b>	<u>Review of Planning and Development Control Framework – Sheet 1 of 2</u>
<b><u>Figure 9.1b</u></b>	<u>Review of Planning and Development Control Framework – Sheet 2 of 2</u>
<b><u>Figure 9.2</u></b>	<u>Landscape Resources</u>
<b><u>Figure 9.3a</u></b>	<u>Photographs of Landscape Resources – Sheet 1 of 3</u>
<b><u>Figure 9.3b</u></b>	<u>Photographs of Landscape Resources – Sheet 2 of 3</u>
<b><u>Figure 9.3c</u></b>	<u>Photographs of Landscape Resources – Sheet 3 of 3</u>
<b><u>Figure 9.4</u></b>	<u>Landscape Character Areas</u>
<b><u>Figure 9.5</u></b>	<u>Photographs of Landscape Character Areas</u>
<b><u>Figure 9.6</u></b>	<u>Visual Envelope and Visually Sensitive Receivers</u>
<b><u>Figure 9.7a</u></b>	<u>Visual Contexts of Visually Sensitive Receivers – Sheet 1 of 4</u>
<b><u>Figure 9.7b</u></b>	<u>Visual Contexts of Visually Sensitive Receivers – Sheet 2 of 4</u>
<b><u>Figure 9.7c</u></b>	<u>Visual Contexts of Visually Sensitive Receivers – Sheet 3 of 4</u>
<b><u>Figure 9.7d</u></b>	<u>Visual Contexts of Visually Sensitive Receivers – Sheet 4 of 4</u>
<b><u>Figure 9.8</u></b>	<u>Recommended Landscape and Visual Mitigation Plan</u>
<b><u>Figure 9.9ai</u></b>	<u>Photomontages – Viewpoint A at VSR 1 – Sheet 1 of 2</u>
<b><u>Figure 9.9a ii</u></b>	<u>Photomontages – Viewpoint A at VSR 1 – Sheet 2 of 2</u>
<b><u>Figure 9.9bi</u></b>	<u>Photomontages – Viewpoint B at VSR 2 – Sheet 1 of 2</u>
<b><u>Figure 9.9b ii</u></b>	<u>Photomontages – Viewpoint B at VSR 2 – Sheet 2 of 2</u>
<b><u>Figure 9.9ci</u></b>	<u>Photomontages – Viewpoint C at VSR 3 – Sheet 1 of 2</u>
<b><u>Figure 9.9c ii</u></b>	<u>Photomontages – Viewpoint C at VSR 3 – Sheet 2 of 2</u>
<b><u>Figure 9.9di</u></b>	<u>Photomontages – Viewpoint D at VSR 4 – Sheet 1 of 2</u>
<b><u>Figure 9.9d ii</u></b>	<u>Photomontages – Viewpoint D at VSR 4 – Sheet 2 of 2</u>
<b><u>Figure 10.1</u></b>	<u>Distribution of Fisheries Production (overall) (Port Survey 2016/17, AFCD)</u>
<b><u>Figure 10.2</u></b>	<u>Distribution of Fishing Vessel Operation (sampan) (Port Survey 2016/17, AFCD)</u>
<b><u>Figure 10.3</u></b>	<u>Distribution of Fishing Vessel Operation (other types of fishing vessels) (Port Survey 2016/17, AFCD)</u>
<b><u>Figure 10.4</u></b>	<u>Distribution of Fisheries Production (sampan) (Port Survey 2016/17, AFCD)</u>
<b><u>Figure 10.5</u></b>	<u>Distribution of Fisheries Production (other types of fishing vessels) (Port Survey 2016/17, AFCD)</u>
<b><u>Figure 10.6</u></b>	<u>Fisheries Resources in the Vicinity of Lai Chi Wo Pier</u>
<b><u>Figure 10.7</u></b>	<u>Locations of Fish Culture Zones in Hong Kong</u>
<b><u>Figure 11.1</u></b>	<u>Assessment Area for Marine Archaeological Investigation</u>
<b><u>Figure 11.2</u></b>	<u>Seabed Features and Distribution of Sonar and Magnetic Contacts</u>

## **Appendices**

<b><u>Appendix 2.1</u></b>	<u>Tentative Construction Programme</u>
<b><u>Appendix 4.1</u></b>	<u>Photos of Representative Noise Sensitive Receivers</u>
<b><u>Appendix 4.2</u></b>	<u>Detailed Plant Inventory</u>
<b><u>Appendix 4.3</u></b>	<u>Locations of Workfronts</u>

<b><u>Appendix 5.1</u></b>	<b><u>Outline of Emergency Spillage Plan</u></b>
<b><u>Appendix 5.2</u></b>	<b><u>Tentative Location for Silt Curtain Deployment</u></b>
<b><u>Appendix 6.1</u></b>	<b><u>Sediment Sampling and Testing Plan</u></b>
<b><u>Appendix 6.2</u></b>	<b><u>Laboratory Testing Results</u></b>
<b><u>Appendix 6.3</u></b>	<b><u>Summary of the Chemical and Biological Screening Tests results</u></b>
<b><u>Appendix 7.1</u></b>	<b><u>Historical Aerial Photos</u></b>
<b><u>Appendix 7.2</u></b>	<b><u>Correspondences with FSD and EPD</u></b>
<b><u>Appendix 7.3</u></b>	<b><u>Photo Records of Site Survey</u></b>
<b><u>Appendix 7.4</u></b>	<b><u>Site Walkover Checklist</u></b>
<b><u>Appendix 8.1</u></b>	<b><u>Plant Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.2</u></b>	<b><u>Mammal Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.3</u></b>	<b><u>Bird Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.4</u></b>	<b><u>Reptile Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.5</u></b>	<b><u>Amphibian Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.6</u></b>	<b><u>Dragonfly Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.7</u></b>	<b><u>Butterfly Species Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.8</u></b>	<b><u>Aquatic Fauna Recorded within the 500m Assessment Area</u></b>
<b><u>Appendix 8.9</u></b>	<b><u>Intertidal Organisms Recorded in the Qualitative Survey within the 500m Assessment Area (Wet Season)</u></b>
<b><u>Appendix 8.10</u></b>	<b><u>Intertidal Organisms Recorded in the Qualitative Survey within the 500m Assessment Area (Dry Season)</u></b>
<b><u>Appendix 8.11</u></b>	<b><u>Intertidal Organisms Recorded in the Quantitative Survey within the 500m Assessment Area (Wet Season)</u></b>
<b><u>Appendix 8.12</u></b>	<b><u>Intertidal Organisms Recorded in the Quantitative Survey within the 500m Assessment Area (Dry Season)</u></b>
<b><u>Appendix 8.13</u></b>	<b><u>Abundance of Subtidal Benthos Species Recorded at each Sampling Location within the 500m Assessment Area during Wet Season</u></b>
<b><u>Appendix 8.14</u></b>	<b><u>Biomass of Subtidal Benthos Species Recorded at each Sampling Location within the 500m Assessment Area during Wet Season</u></b>
<b><u>Appendix 8.15</u></b>	<b><u>Abundance of Subtidal Benthos Species Recorded at each Sampling Location within the 500m Assessment Area during Dry Season</u></b>
<b><u>Appendix 8.16</u></b>	<b><u>Biomass of Subtidal Benthos Species Recorded at each Sampling Location within the 500m Assessment Area during Dry Season</u></b>
<b><u>Appendix 8.17</u></b>	<b><u>Spot Check Dive Survey Results in Lai Chi Wo</u></b>
<b><u>Appendix 8.18</u></b>	<b><u>REA Dive Survey Results in Lai Chi Wo</u></b>
<b><u>Appendix 9.1</u></b>	<b><u>Broad Brush Tree Survey</u></b>
<b><u>Appendix 11.1</u></b>	<b><u>Detailed Results of Side Scan Sonar</u></b>
<b><u>Appendix 11.2</u></b>	<b><u>Image of Processed Magnetic Intensity over the Survey Area</u></b>
<b><u>Appendix 11.3</u></b>	<b><u>Images of Visual Diver Survey</u></b>
<b><u>Appendix 12.1</u></b>	<b><u>Environmental Mitigation Implementation Schedule</u></b>
<b><u>Appendix 14.1</u></b>	<b><u>Key Assessment Assumptions and Limitation of Assessment Methodologies</u></b>
<b><u>Appendix 14.2</u></b>	<b><u>Summary of Environmental Impacts Associated with the Project</u></b>

## **Annexes**

<b><u>Annex 8.1</u></b>	<b><u>Rating of REA Results</u></b>
-------------------------	-------------------------------------